SECKE I IDEALIST

Approved For Release 2002/06/13: CIA-RDP68B00724R000200010001-8

IDEA 0930-69

Copy // of 11

Deputy for Operations, OSA

17 December 1969

WIEWORTH DOWN	OK. See Distribution		
SUBJECT	:	Activity Report - November 1969	
Report for problem within four workin taken, or being tak transmission to the 2. Reques	n areas for which he is g days, appropriate recen, to this component e field. Negative repl	ade by the appropriate Division	- 10
message will be pr	epared by this office f	n of your contribution, a for signature of the DSA, who se message for transmission.	25X1A

Attachment:

25X1A

As stated

Distribution:


- 1 COMPT
- 2 IDEA
- 3 D/M
- 4 SS/OSA
- 5 R&D/OSA
- 6 D/OPS
- 7 DSA
- 8 AMS
- 9 **-** COMMO
- 10 CC/OSA
- -II-RB/OSA

IDEALIST

25X1A

ACTIVITY

REPORT



NOVEMBER 1969

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200010001-8

Approved For Release 2002/06//137 CHA-RDP68B00724R000200010001-8

25X1Å

	· ·	
	Director, OSA	
25X1A	FROM:	
	SUBJECT: Activity Report - Nove	mber 1969
		Page
	A. Summary	1
	B. Operations	2
_0.	C. Materiel	5
25X1A	D. Support/Installations	Activities 14
	E. Life Support	18
	F. Security	21

Approved For Release 2002/06/13 CGA-RDP68B00724R000200010001-8

25X1A

25X1A

ANNEX A

1. SUMMARY

	The highlight of November was the successful completion of
5X1A	the effort to qualify the U-2R and pilots aboard a carrier.
	The smooth manner in which this operation was accomplished speaks
25X1A	well for those individuals in and at who
	were responsible for planning and actions. The Captain
25X1A	and crew of the USS America were especially helpful and cooperative
	throughout the operation.

Approved For Release 2002706/137 GIA-RDP68B00724R000200010001-8

Mirror Landing Practice (MLP) was conducted this month in

ANNEX B

2	•	OPERATIONS	

25X1A 25X1A	preparation for on 20 November. The MLP training was highly successful as was the operation itself. We now have four drivers U2R carrier-qualified. Report has been forwarded to Project Headquarters.
25X1A	Qualification continues to receive utmost attention. It is hoped that all units will soon be OR.
25X1A	2.3. has been completed. RED DOT continues. A long flight to the East Coast has been rescheduled for mid-December. Weather permitting, this flight will complete the current RED DOT series.
	2.4. During the month of December and early January flying will be at a minimum due to aircraft availability. Because of this, several drivers will be unable to maintain Category I Status. However, no degradation of Mission Capability will occur. By February all drivers should be able to again attain Category I Status.
25X1A	2.5. will begin "C" recurrency flights on 9 Decem-
25X1A _.	ber and should complete training prior to departure of It is planned that will assume functions in programs testing in addition to his Operations Officer duties.
	2.6. The following is the month's summary for November 1969:
•	CATEGORY TASKS/SORTIES HOURS
	Training
* .	Low Prof 4 6.1 MLP 31 22.6
·	Config
25X1A	3 11.7
	Systems
25X1A	7.2
25X1A	Special Projects
25X1A,	RED DOT 4 27.3 8.9
*	

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200010001-8

SECRET

•	
Ferry 4	25.4
Maintenance 1	2.0
Maintenance 1	0.4

25X1A

25X1A

SECRET Approved For Release 2002/06/13: CIA-RDP68B00724R000200010001-8

		1		J-2 FL	T33A					
PILOT		TOT SOR	AL TIES	SORT	L 3.5 IES	TOTAL	HOURS	SORTIES	Hours	
1	···	С	R	С	R	С	R			
		0	3	0	1	0	7.0	2	4.0	
		0	2	. 0	1	0	7.2	4	7.3	
		3	8	3	. 0	15.8	. 7.4	1	2.0	
		0	1	. 0.	1	0	4.8	3	5,3	
		0	8	0	· 1	. о	17.5	1	1.3	
		0	10	0	2	0	19.5	. 0	0	
	•	0	10	0	. 2	0	19.1	0	0	
	-	1	1	1	0	4.4	2.0	2	4.0	
		0	2	0	0	0	4.5	3	4.9	
		0	9	0	0	0	7.6	N/A	N/A	
•	1900 - Anna Anna Anna Anna Anna Anna Anna An									
rotals :		4	54	4	8	20.2	96.6	16	28.8	
REMARKS:	,		•		**************************************					
8. U-2 AIRO	RAFT UT	ILIZA	TION I	RATES	-					
AVERAGE	NUMBER A	AIRCR	AFT PO	OSSESSI	ED	••••	• • • • • •	6.1		
AVERAGE	NUMBER A	IRCR	AFT F1	YABLE.	STORAG	, T		2.0		

AVERAGE NUMBER AIRCRAFT POSSESSED. 6.1

AVERAGE NUMBER AIRCRAFT FLYABLE STORAGE. 2.0

AVERAGE NUMBER AIRCRAFT IN/OR. 4.1

AVERAGE NUMBER SORTIES PER AIRCRAFT. 14.1

AVERAGE NUMBER HOURS FLOWN PER AIRCRAFT. 28.5

TOTAL SORTIES FLOWN. 58

TOTAL HOURS FLOWN. 116.8

Approved For Release 2002/06/13: CIA-RDP68B00724R000200010001-8

SECRET

25X1A

Approved For Release 2002/96/13: CTA-RDP68B00724R000200010001-8

ANNEX C

3. MATERIEL

3.1. Tactical Aircraft Maintenance

- 3.1.1. Articles 348 and 349 remained in flyable storage during this reporting period.
- 3.1.2. Article 383 completed four scheduled sorties in November and was in "Ready" status the entire period requiring only routine maintenance.
- 3.1.3. Article 051 was out of commission briefly on 4 November as postflight inspection revealed a hydraulic leak in the aft engine compartment. Engine roll back was required and replacement of two "O" rings at the flap selector valve corrected the condition. Article was transferred to ______ on 10 November for a subsequent 75 day loan period.

25X1A

25X1A

25X1A

25X1A

25X1A

3.1.4. Article 053 entered periodic inspection and update on 4 November following a twelve hour Red Dot sortie. Twenty-five service bulletins were incorporated during this inspection. Functional check flight completing the inspection was flown on 21 November. Article entered "In Commission" status following this sortie with O.R. status pending sortie which was flown on 25 November. Subsequent readout of this sortie was unsatisfactory and another flight will be necessary when article returns to Article was transferred to on 26 November for installation.

3.1.5. Article 054 was out of commission the first part of November for incorporation of Service Bulletin 351-262, AFCS modification. A combined YAuto Pilot check sortie was flown on 6 November. This flight was satisfactory, however article was again taken out of commission for MLG modification and RX-107 kit installation (arresting hook) which was completed on 8 November. Article was involved in a non-delivery on 10 November when on postflight the A.C. generator would not drop off the line when reducing the power lever to idle. Corrective action was the replacement of the monitored A.C. contactor relay and the supervisory panel. On 11 November, an aggressive flight schedule began as fourteen MLP sorties were completed through 17 November in preparation for the exercise. article deployed on ferry flight on 20 November as backup for Article 055. There were no carrier traps made with this article since Article 055 was utilized for all scheduled sorties. Article returned to on 24 November.

3.1.6. Article 055, as the prime article for the exercise, completed seventeen MLP sorties through 18 November. Ferry departure from was made on 20 November. Following this ferry flight, post flight inspection revealed an oil leak at the CSD hydro cooler which required replacement. R-model aircraft were successfully "carrier qualified" as were

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200010001-8

⁵ SECRET

25X1D

25X1D 25X1A 25X1A

25X1A

25X1A

25X1A

25X1A

Approved For Release 20020613. CA-RDP68B00724R000200010001-8

driver. Aircraft fueling, movement and storage on the carrier presented no problems. Although the exercise was very successful and went relatively smooth, it was not entirely uneventful. Unscheduled aircraft maintenance included replacement of the left hand tail landing gear door rod on one occasion and the left hand tail landing gear door on two occasions. These replacements were the result of damage incurred on three of the trap landings.

3.2. Support Aircraft Maintenance

25X1A

3.2.1. T-33 S/N was out of commission a total of four days which constituted a Phased Inspection. U-3B S/N was out of commission three days which was also due to a Phased Inspection.

3.2.2. The average "In-Commission" rate for all assigned support aircraft was 95.5% for the month of November.

3.2.3. Six transient aircraft were supported during the month.

THE REMAINING PORTION OF THIS PAGE INTENTIONALLY LEFT BLANK

25X1A

3.3. Aircraft ctivity SECRET Approved For Robase 2002/06/13 CM RDP68B00724R000200010001-8

				Ž.		λ		TYPE	MISS	NOIS			ΛI	R A	BOR	rs		G!	เดบ:	ZD ,	ABO	RTS	
ARTICLE	ARTICLE	FLTS SCHED	TAKOO SITA	HOURS FLOWN	Z IN CONFI	% OPS READY	Oper	Hq Dir	Trng	Maint	Ferry	Acft	Avion	Config	Wx	ops.	Other	Acft	Avion.	Config	l/X	Ops	Other
Ŭ-2 <u>G</u>	348	0	0	0	100	N/A													·				
U-2G	349	0	0	0	100	N/A																	
U−2 C	383	4	4	20.2	-	100			4										•				
U-2R	051	3	3	7.8	. <u>.</u> .	90			3														
U-2 <u>R</u>	053	3	3	17.6	20	17			2	1													
U-2R	054	19 -	19	30.2	6	75			17		2												
U-2R	055	29	29	41.0	-	82			26	1.	2												
U-2		-								·													
TOTAL		58	58	116. 8		73			52	2	4												
T-33A		10	6	14.7	84	N/A																4	
T-33A		10	6	16.4	100	N/A															-	4	
T-33A		10	9	32.9	100	N/A						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1										1	
U- 3A		16	15	41.6	100	N/A																1	-
U-3B		13	13	30.6	89	N/A																	
C-210		12	12	7.5	100	N/A																	
25X1A TOTAL		71	App	143. rove⁄d	95. Foß F	eleas	26	07/98			KDP6	B00	724	ROO	920	001	900	1-8				10	

3,4. System/Article Discrepancy Summary

Approved For Release 2002/06/13 CIA-RDP68B00724R000200010001-8 Note:

	17	UMBER OF		TOTAL	PERCENTAGE			
System	 		RTICLI					
SISIRI	383	. 051	053	054	055		PER SYSTEM	PER SYSTEM
1. Acft Gen	1	1	2		4		8	20%
3. Hydro		2			2		4	9%
4. Elect				2	3		5	12%
5. Instr	1			1.			2	5%
7. A/P	1	3		2	1		.7	18%
8. Driftsight			1				1	3%
11. ARC-51			•	1			1	3%
14. AIC-10 ·				3			3	8%
16. ADF			1				1	3%
19. IFF				1	1		2 .	5%
25X1D						1 11		11
			'					
	1)							
•								
4								
· · · · · · · · · · · · · · · · · · ·								
· · · · · · · · · · · · · · · · · · ·								
· · · · · · · · · · · · · · · · · · ·								
TOTAL T	3	0000000		12				
	3 ur Release 2	6 2002/06/13 16%		12 RDP6 30%	12 8B007	24R00		100%

Next 2 Page(s) In Document Exempt

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200010001-8

25X1A

25X1A

3.9. Unit Supply

25X1A 25X1A

3.9.1. The first of two C-130 missions supporting departed 14 November on schedule with a cargo load of 7,803 pounds marked for ship prepositioning. The second aircraft departed 19 November with cargo load of 17,244 pounds for beach prepositioning. All cargo returned intact. No resupply problems arose that could not be rectified by 3.9.2. Supply activity: . FAK Turn-Ins......123 L/I SLOE Changes... Accounts Under Inventory...... 3 ea SPARES SHIPMENTS AND RECEIPTS Receipts requested by us................549 L/I Long distance runs over 70 miles...12 (7.5 man days) Total documents used - November......428

SECRET Approved For Release 2002/06/13 : CIA-RDP68B00724R009200010001-8

3.10. Remarks

25X1A	3.10.1. November was a full month, highlighted by the successful Exercise. The articles performed exceptionall well in spite of frustrating human lapses that reflected poorly on us humans but that discredited the birds not at all. Now that the U-2 is tightened up, internal people tightening is in order and is being accomplished.						

3.10.4. Support maintenance had an outstanding effective month. With six aircraft and six people assigned, one of whom was on leave most of the month, the eager beavers accomplished the following:

3.10.4.1. Flew 61 sorties for 143.7 hours.

25X1D

3.10.4.2. Had no aborts, air or ground.

3.10.4.3. Had no maintenance non-deliveries.

3.10.4.4. Completed two phased inspections

3.10.4.5. Maintained an overall in-commission

rate of 95.5%

The numbers tell their own story.

Next 2 Page(s) In Document Exempt

Approved For Release 2002/08 3 RIA-RDP68B00724R000200010001-8

4.2. <u>Installations</u>

25X1A

4.2.1. The contract for the re-roofing of Hangar # 1 was completed on 10 November 1969 after the installation of four (4) pilot doors, boiler room double doors and painting of same after work accomplished. Necessary corrections to the previously installed roof ventilators were also made.

25X1A

4.2.2. The relocation of the perimeter fence and related lighting system around the new POL Truck Parking Lot was basically accomplished between 4 and 16 November 1969. Additional light poles and related electrical wiring has been progressing according to schedule. The grading and compacting of the parking lot is near readiness for blacktopping in early December as well as the roadway for the LOX facilities. The only difficulty encountered to date in this contract is with the airplane wash rack facility. The water piping as installed in accordance with the drawings was found to be inadequate since it was connected to a non-pressured well line. No solution has been reached to date but a change order will be necessary to disconnect and extend to new line to a more distant source. Civil Engineering is now attempting to solve this problem with minimum cost.

25X1A

25X1A


4.3. and Associates Activities


25X1A


4.3.2. During the month of November, drawings and specifications were being prepared for the new asphaltic paved surfaces, including chain link fence enclosure around the Inspection Building. Also being prepared are plans that are required for the modifications to Tower # 5. It is anticipated that the plans for the tower modifications will be completed and submitted to ______ the first week in December. The plans and specifications for the bituminous paving operations will be submitted in December, as soon as final typing of specifications are completed.


Approved For Release 2002/06/18 - CINERDP68B00724R000200010001-8

5.1.2. Medical Activities













Approved For Release 2002/06/18 CIA-RDP68B00724R000200010001-8

5.2.2 FLIGHT SUPPORT









Approved For Release 2002/06/13 : CIA-RDP68B00724R000200010001

Approved For Release 2002/06/13: CIA-RDP68B00724R000200010001-8

	6. SECURITY	
25X1A	6.1. <u>Liaison</u>	
25X1A	conferred with and the contract security person- ner. This meeting afforded the contract security personnel an opportun- ity for private discussions concerning their job status, salary and/or any problems relating to their position at this installation.	
	6.2. Support	
25X1A		
	6.3. Courier Activities	
*	6.3.1. During this reporting period the Detachment's contract Security assistants completed four domestic runs. The total distance flown on the four runs amounted to 39,400 miles.	
,	6.4. Remarks	
	6.4.1. During this period, met with all members	

of the Detachment's Security Staff. Personnel matters such as overtime pay, assignments, TDY travel were discussed and reviewed. Also discussed

at this meeting were matters pertaining to the Detachment's general security posture. Everyone present was afforded an opportunity to voice their opinion and offer suggestions that would be beneficial to the

security functions of this detachment.

25X1A

SECRET

to the first of th

Carlon and